





Systémy **KOVÁNÍ KŘÍDLOVÝCH BRAN A VRAT**

Panty k našroubování bez nutnosti navařování na sloupky



	F	H	S	I	L	M	A	G	D	díra v sloupku
PAE M18	M18	39	6	21	127	104	30	52-58	45	35
PAE M20	M20	39	6	21	131	104	30	56-63	50	40
PAE M22	M22	41	6	23	131	104	30	58-69	50	40